

Trail/Road Coating for Snowmobile Crossings

- Project Number 2012-02
 - Project Leader Jeannine Briol
 - Agency Scott County 600 Country Trail East Jordan, MN 55352
 - **Phone** 952-496-8027



Problem Snowmobiles often cause damage to pavement when they cross trails and roads, requiring

repairs to be made earlier than in non-crossing areas. The trails are often used for biking and rollerblading, which require a smooth, undamaged trail for safety reasons.

- **Solution** The county installed a thermoplastic coating attained from P.K. Contracting in Troy, Michigan, to minimize or eliminate this problem on roads and trail systems.
- **Procedure** The material was placed at crossing locations on roads and trails in September 2013, prior to the winter snowfall season. The product was placed in a hopper on a flatbed truck and heated to 420°F. It was then transferred to a small pushcart machine, which placed the material and scattered silica sand behind. Silica sand was also spread by hand to ensure even distribution.

The product was placed in a series of 12-inch strips starting from centerline. Three layers were placed with each layer offset 6 inches in from the previous layer to prevent snowplows from peeling off the material. Silica sand was placed along each strip to increase the bond between layers, to prevent vehicle tires from peeling it up before it fully cured, and to provide friction for drivers. The process took approximately an hour in each location, and traffic was allowed on the roadway within 10 minutes of placement.

Results County officials kept track of how many snowmobiles crossed the roads and trails for two years and evaluated the condition of the coating and pavement each spring. The coating held up very well through both winters, requiring only basic maintenance procedures such as plowing and salting. Damage at locations where snowmobiles cross was very minimal compared to locations without the thermoplastic coating.

Approximate Cost \$10,328

- **OPERA Funding** \$7,600
- **Implementation** The county anticipates future cost savings because the protection offered by the coating will reduce the need to repair the roadway in the crossing area. If the treated area continues to prevent damage to the roadway from snowmobiles as it has for its first two years, county staff will be able to use the regular maintenance schedule.
 - Status Complete

Prepared by:

Minnesota Local Technical Assistance Program (LTAP) Center for Transportation Studies University of Minnesota 200 Transportation and Safety Building 511 Washington Avenue S.E. Minneapolis, MN 55455-0375 Phone: 612-626-1077 Fax: 612-625-6381 E-mail: mnltap@umn.edu Web: www.mnltap.umn.edu

Local OPERA Program partners: Minnesota Local Road Research Board (LRRB), Minnesota Department of Transportation (MnDOT), and Minnesota Local Technical Assistance Program (LTAP) at the Center for Transportation Studies, University of Minnesota.

Any product mentioned within should not be considered a product endorsement. Authors' opinions/findings do not necessarily reflect the views of the Local OPERA Program.



MINNESOTA LTAP center for transportation studies University of Minnesota



The University of Minnesota is an equal opportunity educator and employer. This publication is available in alternative formats upon request.